

### Ugly Tanker

#### Before and After Tanker Refurbishment

These 6,200-gallon tank containers were destined for the Caribbean but before they could be loaded with aviation fuel they needed GEM 360 to recondition them. Because of the salt water exposure this tank would be exposed to in its new home, it needed the specialized care that GEM 360 is well known for in the industry.

The tank was first water jet blasted to remove rust, old paint, and scaling. Next, it was sanded, given a coat of primer and coated with high-quality paint especially used for tank containers. The final step was installing their graphics. A true 360-degree exterior makeover!

